





Land Subsidence at Survey Mark SS3315 Half way up Rewa Rd




Land Subsidence at Survey Mark SS 3316 Top of Rewa Road







Land Subsidence at Survey Mark AP13 End of Barrister Avenue nearest the Quarry




Land Subsidence at Survey Mark AP6 Near the School Gates on Queensway




Land Subsidence at Survey Mark AP31 Near Corinne's Place




Land Subsidence at Survey Mark AP21 Corner of Kingsway and Mt Eden Rd




Land Subsidence at Survey Mark AP206 Corner of Mt Albert Road and Buckley Road




Land Subsidence at Survey Mark AP12 Peak of Warren Ave




Land Subsidence at Survey Mark OAP19 St Andrews Road near the tennis courts




Land Subsidence at Survey Mark M210 Corner of Mt Albert Road and Warren Ave







Land Subsidence at Survey Mark RM3889 Corner of Duke St and Hamon Ave




Land Subsidence at Survey Mark RM3893 Duke Street shops










Land Subsidence at Survey Mark RM 7647 Corner of Mt Albert Road and Rowan Road




Land Subsidence at Survey Mark SM1979 On Hillsborough Road near Budock Road





Land Subsidence at Survey Mark SM4354 Corner of Mt Eden Rd and Rewa Rd



Land Subsidence at Survey Mark SM6809 Corner of Gorrie Ave and St Andrews Rd

